The Mint of the Anited States at Philadelphia,

Superintendent's Office,

Jone 9 - , 1894.

Gent George & Sunden Chief Clark

Enclased for mile find the report of Capt Octman night track reporting a fine in the buildings to --coted in Die Rom Engraving Defer Cause of fin, Hot die or die in annealing box, igniting the chancel and burning side of box. and from this the Wainscoting, dumane Slight, and have ordered a brick wall places amont the loca

dion for feetine safely and Instestion. The reference needed con be furnished by the Mind most . I have been enterment by reporters and said slight fire from annealing Box and Jus Rispectfully James Ellac Line Hinz 9. 1894

The Mint of the United States at Philadelphia, Superintendent's Office, June 9, 1894

Genl. George R. Sumder Chief Clerk

Sir

Enclosed you will find the report of Capt. Pitman night watch reporting a fire in the building located in "Die Room" Engraving Dept. cause of fire, hot die or dies in annealing box, igniting the charcoal and burning side of box, and from this the wainscoting, damage slight, and have ordered a brick wall placed around the location for future safety and protection. The repairs needed can be furnished by the Mint and our own men doing the work. Have been interviewed by reporters and said "slight fire from annealing box and no damage".

Yours Respectfully James E. MacLaue Custodian